
HK TS TP
Temperature sensor

Properties

Material	Stainless steel
Use	For gauge HK PTQCheck





Description

Measurement range -50 °C to +120 °C
Measuring accuracy ±0.2 °C
Outer thread 1/4" fitting
Output signal 4 to 20 mA

Ordering information

Further accessories and gauges with additional options available on request.

Item

Identification	Measuring range	Pressure max. (bar)	Overload pressure max. (bar)	Connection	Weight (kg)
HK TS TP 140	-50 to +120 °C	400	420	G 1/4" - male thread	0,1

Accessory for following products

HK PTQ CHECK	Digital hand-held gauge, 5-channels

Additional elements

HK PML	Single instrumentation cable
HK PQT	Combination instrumentation cable

Despite careful checking, we cannot guarantee the accuracy of all information included on this site, and we accept no liability.