

# RMM 100

Pressure gauges without glycerine filling

**HANSA FLEX**

## Properties

<b>Design</b>	Pipe spring pressure gauge without glycerine filling
<b>Connection 1</b>	BSP external thread, cylindrical
<b>Sealing form 1</b>	flat seal with pin
<b>Connection</b>	at bottom
<b>Standard</b>	EN 837-1
<b>Temp. range</b>	medium max. +60 °C Ambient -20 °C to +60 °C



## Note

Application range at idle load: 3/4 x full scale.

Application range with alternating load: 2/3 x full scale.

## Item

Identification	Nominal size Ø	Scale range	Quality class	Connection
RMM 100-0.6	100	0...0,6	1,6	G 1/2" -14
RMM 100-1	100	0...1	1,6	G 1/2" -14
RMM 100-1.6	100	0...1,6	1,6	G 1/2" -14
RMM 100-2.5	100	0...2,5	1,6	G 1/2" -14
RMM 100-4	100	0...4	1,6	G 1/2" -14
RMM 100-6	100	0...6	1,6	G 1/2" -14
RMM 100-10	100	0...10	1,6	G 1/2" -14
RMM 100-16	100	0...16	1,6	G 1/2" -14
RMM 100-25	100	0...25	1,6	G 1/2" -14
RMM 100-40	100	0...40	1,6	G 1/2" -14
RMM 100-60	100	0...60	1,6	G 1/2" -14
RMM 100-100	100	0...100	1,6	G 1/2" -14
RMM 100-160	100	0...160	1,6	G 1/2" -14
RMM 100-250	100	0...250	1,6	G 1/2" -14
RMM 100-315	100	0...315	1,6	G 1/2" -14
RMM 100-400	100	0...400	1,6	G 1/2" -14