

# RMM 80 H 1/4

Pressure gauges without glycerine filling

**HANSA FLEX**

## Properties

<b>Design</b>	Pipe spring pressure gauge without glycerine filling
<b>Connection 1</b>	BSP external thread, cylindrical
<b>Sealing form 1</b>	flat seal with pin
<b>Connection</b>	on back, centric
<b>Standard</b>	EN 837-1
<b>Temp. range</b>	medium max. +60 °C Ambient -20 °C to +60 °C



## Note

Application range at idle load: 3/4 x full scale.

Application range with alternating load: 2/3 x full scale.

## Item

Identification	Nominal size Ø	Scale range	Quality class	Connection
RMM 80-0.6 H 1/4	80	0...0,6	1,6	G 1/4" -19
RMM 80-1 H 1/4	80	0...1	1,6	G 1/4" -19
RMM 80-1.6 H 1/4	80	0...1,6	1,6	G 1/4" -19
RMM 80-2.5 H 1/4	80	0...2,5	1,6	G 1/4" -19
RMM 80-4 H 1/4	80	0...4	1,6	G 1/4" -19
RMM 80-6 H 1/4	80	0...6	1,6	G 1/4" -19
RMM 80-10 H 1/4	80	0...10	1,6	G 1/4" -19
RMM 80-16 H 1/4	80	0...16	1,6	G 1/4" -19
RMM 80-25 H 1/4	80	0...25	1,6	G 1/4" -19
RMM 80-40 H 1/4	80	0...40	1,6	G 1/4" -19
RMM 80-60 H 1/4	80	0...60	1,6	G 1/4" -19
RMM 80-160 H 1/4	80	0...160	1,6	G 1/4" -19
RMM 80-250 H 1/4	80	0...250	1,6	G 1/4" -19
RMM 80-315 H 1/4	80	0...315	1,6	G 1/4" -19
RMM 80-400 H 1/4	80	0...400	1,6	G 1/4" -19