

RVM 100

Vacuum pressure gauges without glycerine filling

HANSA FLEX

Properties

| | |
|-----------------------|--|
| Design | Pipe spring pressure gauge without glycerine filling |
| Connection 1 | BSP external thread, cylindrical |
| Sealing form 1 | flat seal with pin |
| Connection | at bottom |
| Standard | EN 837-1 |
| Temp. range | medium max. +60 °C Ambient -20 °C to +60 °C |



Note

Application range at idle load: 3/4 x full scale.

Application range with alternating load: 2/3 x full scale.

Item

| Identification | Nominal size Ø | Scale range | Quality class | Connection |
|-----------------|----------------|-------------|---------------|------------|
| RVM 100 -1 +0 | 100 | -1...0 | 1,6 | G 1/2" -14 |
| RVM 100 -1 +0.6 | 100 | -1...+0,6 | 1,6 | G 1/2" -14 |
| RVM 100 -1 +1.5 | 100 | -1...+1,5 | 1,6 | G 1/2" -14 |
| RVM 100 -1 +3 | 100 | -1...+3 | 1,6 | G 1/2" -14 |
| RVM 100 -1 +5 | 100 | -1...+5 | 1,6 | G 1/2" -14 |
| RVM 100 -1 +9 | 100 | -1...+9 | 1,6 | G 1/2" -14 |
| RVM 100 -1 +15 | 100 | -1...+15 | 1,6 | G 1/2" -14 |