

RVM 100

Vacuum pressure gauges without glycerine filling

HANSA FLEX

Properties

Design	Pipe spring pressure gauge without glycerine filling
Connection 1	BSP external thread, cylindrical
Sealing form 1	flat seal with pin
Connection	at bottom
Standard	EN 837-1
Temp. range	medium max. +60 °C Ambient -20 °C to +60 °C



Note

Application range at idle load: 3/4 x full scale.

Application range with alternating load: 2/3 x full scale.

Item

Identification	Nominal size Ø	Scale range	Quality class	Connection
RVM 100 -1 +0	100	-1...0	1,6	G 1/2" -14
RVM 100 -1 +0.6	100	-1...+0,6	1,6	G 1/2" -14
RVM 100 -1 +1.5	100	-1...+1,5	1,6	G 1/2" -14
RVM 100 -1 +3	100	-1...+3	1,6	G 1/2" -14
RVM 100 -1 +5	100	-1...+5	1,6	G 1/2" -14
RVM 100 -1 +9	100	-1...+9	1,6	G 1/2" -14
RVM 100 -1 +15	100	-1...+15	1,6	G 1/2" -14