

# RVM 40 HFR

Vacuum pressure gauges without glycerine filling

**HANSA FLEX**

## Properties

<b>Design</b>	Pipe spring pressure gauge without glycerine filling
<b>Mounting</b>	Front ring with mounting bores
<b>Connection 1</b>	BSP external thread, cylindrical
<b>Sealing form 1</b>	flat seal with pin
<b>Connection</b>	on back, centric
<b>Standard</b>	EN 837-1
<b>Temp. range</b>	medium max. +60 °C Ambient -20 °C to +60 °C



## Note

Application range at idle load: 3/4 x full scale.

Application range with alternating load: 2/3 x full scale.

## Item

Identification	Nominal size Ø	Scale range	Quality class	Connection
RVM 40 -1 +0 HFR	40	-1...0	2,5	G 1/4" -19
RVM 40 -1 +0.6 HFR	40	-1...+0,6	2,5	G 1/4" -19
RVM 40 -1 +1.5 HFR	40	-1...+1,5	2,5	G 1/4" -19
RVM 40 -1 +3 HFR	40	-1...+3	2,5	G 1/4" -19
RVM 40 -1 +5 HFR	40	-1...+5	2,5	G 1/4" -19
RVM 40 -1 +9 HFR	40	-1...+9	2,5	G 1/4" -19
RVM 40 -1 +15 HFR	40	-1...+15	2,5	G 1/4" -19