

# GMM 100 H

Manometar sa glicerinskim punjenjem

**HANSA FLEX**

## Osobine

Konstrukcija	Pipe spring pressure gauge with glycerine filling
Priključak 1	BSP spoljni cilindrični navoj
Oblik zaptivke 1	ravno zaptivanje sa rukavcem
Priključak	pozadi, ekscentrično
Norma	EN 837-1
Prigušivanje	pomoću glicerinskog punjenja
Temperaturni opseg	medija maks. +60 °C Okoline -20 °C do +60 °C



## Napomena

Područje primene kod mirnog opterećenja: 3/4 x vrednost na skali.

Područje primene kod promenljivog opterećenja: 2/3 x vrednost na skali.

## Artikal

Naziv	Nominalna veličina Ø	Opseg skale	Klasa kvaliteta	Priključak
GMM 100-0.6 H	100	0...0,6	1,0	G 1/2" -14
GMM 100-1 H	100	0...1	1,0	G 1/2" -14
GMM 100-1.6 H	100	0...1,6	1,0	G 1/2" -14
GMM 100-2.5 H	100	0...2,5	1,0	G 1/2" -14
GMM 100-04 H	100	0...4	1,0	G 1/2" -14
GMM 100-06 H	100	0...6	1,0	G 1/2" -14
GMM 100-10 H	100	0...10	1,0	G 1/2" -14
GMM 100-16 H	100	0...16	1,0	G 1/2" -14
GMM 100-25 H	100	0...25	1,0	G 1/2" -14
GMM 100-40 H	100	0...40	1,0	G 1/2" -14
GMM 100-60 H	100	0...60	1,0	G 1/2" -14
GMM 100-100 H	100	0...100	1,0	G 1/2" -14
GMM 100-160 H	100	0...160	1,0	G 1/2" -14
GMM 100-250 H	100	0...250	1,0	G 1/2" -14
GMM 100-400 H	100	0...400	1,0	G 1/2" -14
GMM 100-600 H	100	0...600	1,0	G 1/2" -14