

# GMM 100 H

## 注有甘油的压力表

### 属性

|        |   |
|--------|---|
| 结构类型   | Pipe spring pressure gauge with glycerine filling |
| 接口 1   | BSP外螺纹,圆柱形  |
| 密封形式 1 | 带塞扁平密封  |
| 接口     | 后,偏心  |
| 标准     | EN 837-1  |
| 缓冲     | 通过甘油注入  |
| 温度范围   | medium max. +60 °C<br>Ambient -20 °C to +60 °C    |



### 提示

静止负荷时应用范围: 3/4 x 刻度盘终端读数。

交变负荷时应用范围: 2/3 x 刻度盘终端读数。

### 货品

| 名称            | 额定大小 Ø | 刻度范围    | 质量等级 | 接口         |
|---------------|--------|---------|------|------------|
| GMM 100-0.6 H | 100    | 0...0,6 | 1,0  | G 1/2" -14 |
| GMM 100-1 H   | 100    | 0...1   | 1,0  | G 1/2" -14 |
| GMM 100-1.6 H | 100    | 0...1,6 | 1,0  | G 1/2" -14 |
| GMM 100-2.5 H | 100    | 0...2,5 | 1,0  | G 1/2" -14 |
| GMM 100-04 H  | 100    | 0...4   | 1,0  | G 1/2" -14 |
| GMM 100-06 H  | 100    | 0...6   | 1,0  | G 1/2" -14 |
| GMM 100-10 H  | 100    | 0...10  | 1,0  | G 1/2" -14 |
| GMM 100-16 H  | 100    | 0...16  | 1,0  | G 1/2" -14 |
| GMM 100-25 H  | 100    | 0...25  | 1,0  | G 1/2" -14 |
| GMM 100-40 H  | 100    | 0...40  | 1,0  | G 1/2" -14 |
| GMM 100-60 H  | 100    | 0...60  | 1,0  | G 1/2" -14 |
| GMM 100-100 H | 100    | 0...100 | 1,0  | G 1/2" -14 |
| GMM 100-160 H | 100    | 0...160 | 1,0  | G 1/2" -14 |
| GMM 100-250 H | 100    | 0...250 | 1,0  | G 1/2" -14 |
| GMM 100-400 H | 100    | 0...400 | 1,0  | G 1/2" -14 |
| GMM 100-600 H | 100    | 0...600 | 1,0  | G 1/2" -14 |