

GMM 50

Pressure gauges with glycerine filling

HANSA FLEX

Properties

| | |
|-----------------------|---|
| Design | Pipe spring pressure gauge with glycerine filling |
| Connection 1 | BSP external thread, cylindrical |
| Sealing form 1 | flat seal with pin |
| Connection | at bottom |
| Standard | EN 837-1 |
| Damping | due to glycerine filling |
| Temp. range | medium max. +60 °C Ambient -20 °C to +60 °C |



Note

Application range at idle load: 3/4 x full scale.

Application range with alternating load: 2/3 x full scale.

Item

| Identification | Nominal size Ø | Scale range | Quality class | Connection |
|----------------|----------------|-------------|---------------|------------|
| GMM 50-1 | 50 | 0...1 | 2,5 | G 1/4" -19 |
| GMM 50-1.6 | 50 | 0...1,6 | 2,5 | G 1/4" -19 |
| GMM 50-2.5 | 50 | 0...2,5 | 2,5 | G 1/4" -19 |
| GMM 50-4 | 50 | 0...4 | 2,5 | G 1/4" -19 |
| GMM 50-6 | 50 | 0...6 | 2,5 | G 1/4" -19 |
| GMM 50-10 | 50 | 0...10 | 2,5 | G 1/4" -19 |
| GMM 50-16 | 50 | 0...16 | 2,5 | G 1/4" -19 |
| GMM 50-25 | 50 | 0...25 | 2,5 | G 1/4" -19 |
| GMM 50-40 | 50 | 0...40 | 2,5 | G 1/4" -19 |
| GMM 50-60 | 50 | 0...60 | 2,5 | G 1/4" -19 |
| GMM 50-100 | 50 | 0...100 | 2,5 | G 1/4" -19 |
| GMM 50-160 | 50 | 0...160 | 2,5 | G 1/4" -19 |
| GMM 50-250 | 50 | 0...250 | 2,5 | G 1/4" -19 |
| GMM 50-400 | 50 | 0...400 | 2,5 | G 1/4" -19 |