


HFM MK OR VA

Measuring connection, M16 x 2 series

HANSA FLEX

Properties

Connection 1	metric cylindrical outer thread
Sealing form 1	O-ring seal on screw-in socket
Connection 2	Measuring connection M 16 x 2
Design	Screw-in socket with measurement connection
Scope of supply	with cap
Temp. min.	-20 °C
Temp. max.	100 °C
Material	Stainless steel



Item

Identification	G1	Max. working pressure (bar)	OR
HFM MK 08-1 OR VA	M 8 x 1	630	6.1 x 1.6
HFM MK 10-1 OR VA	M 10 x 1	630	8.0 x 1.5