

# HFM MK OR VA

Measuring connection, M16 x 2 series

**HANSA FLEX**

## Properties

<b>Connection 1</b>	metric cylindrical outer thread
<b>Sealing form 1</b>	O-ring seal on screw-in socket
<b>Connection 2</b>	Measuring connection M 16 x 2
<b>Design</b>	Screw-in socket with measurement connection
<b>Scope of supply</b>	with cap
<b>Temp. min.</b>	-20 °C
<b>Temp. max.</b>	100 °C
<b>Material</b>	Stainless steel



## Item

Identification	G1	Max. working pressure (bar)	OR
HFM MK 08-1 OR VA	M 8 x 1	630	6.1 x 1.6
HFM MK 10-1 OR VA	M 10 x 1	630	8.0 x 1.5