

# RVM 63 HKR

Vacuum pressure gauges without glycerine filling

**HANSA FLEX**

## Properties

|                       |  |
|-----------------------|--|
| <b>Design</b>         | Pipe spring pressure gauge without glycerine filling |
| <b>Mounting</b>       | Clamping ring  |
| <b>Connection 1</b>   | BSP external thread, cylindrical                     |
| <b>Sealing form 1</b> | flat seal with pin                                   |
| <b>Connection</b>     | on back, centric                                     |
| <b>Standard</b>       | EN 837-1   |
| <b>Temp. range</b>    | medium max. +60 °C<br>Ambient -20 °C to +60 °C       |



## Note

Application range at idle load: 3/4 x full scale.

Application range with alternating load: 2/3 x full scale.

## Item

| Identification     | Nominal size Ø | Scale range | Quality class | Connection |
|--------------------|----------------|-------------|---------------|------------|
| RVM 63 -1 +0 HKR   | 63             | -1...0      | 2,5           | G 1/4" -19 |
| RVM 63 -1 +0.6 HKR | 63             | -1...+0,6   | 2,5           | G 1/4" -19 |
| RVM 63 -1 +1.5 HKR | 63             | -1...+1,5   | 2,5           | G 1/4" -19 |
| RVM 63 -1 +3 HKR   | 63             | -1...+3     | 2,5           | G 1/4" -19 |
| RVM 63 -1 +5 HKR   | 63             | -1...+5     | 2,5           | G 1/4" -19 |
| RVM 63 -1 +9 HKR   | 63             | -1...+9     | 2,5           | G 1/4" -19 |
| RVM 63 -1 +15 HKR  | 63             | -1...+15    | 2,5           | G 1/4" -19 |