## BOX Schnur

Boxed set cord & tools

## HANSA/FLEX

rioperaes	
Design	O-ring cord
Scope of supply	Blade, cutting device, adhesive, measuring tape
Colour	Box, red
Temp. min.	-30 °C
Temp. max.	100 °C
Material	NBR 70 Shore



d (mm)	NBR	FPM
1,78	2 m	1 m
2,00	2 m	1 m
2,40	2 m	1 m
2,62	2 m	1 m
3,00	2 m	1 m
3,53	2 m	1 m
4,00	2 m	1 m
4,50	2 m	1 m
5,00	2 m	1 m
5,34	2 m	1 m
5,70	2 m	1 m
6,00	2 m	1 m
7,00	2 m	1 m
8,00	2 m	1 m

Identification

BOX CORD NBR