


# K-VAKUUMSENSOR ANALOG

Vacuum sensor, analogue

**HANSA FLEX**

## Características

<b>Aplicación</b>	Measurement of vacuum values close to the suction pad Remote evaluation of the signals Processing the output signals, for example, by PLC
<b>Medios</b>	dry, oil-free air and non-aggressive gases
<b>Rango de temperatura</b>	0 - 50 °C
<b>Señal de salida</b>	1 to 5 analogous to V
<b>Histéresis</b>	Fixed: 20 mbar (model with digital sensor)
<b>Long. cable</b>	3 m
<b>Tipo de protecc.</b>	IP 40



## Nota

Otras especificaciones a petición.

## Descripción

Mini-sensor with housing and connection cable, analogue or digital output signal. Minimum size and low weight combined with high measuring accuracy.

## Artículo

Denominación	Conexión	H (mm)	L (mm)	Rango de medición	Tensión
K- 07 45 01 56	M 5 male	16,9	21,0	-1 bis 0 bar	10 - 24 V DC