

K-VAKUUMSENSOR ANALOG

Vacuum sensor, analogue

HANSA FLEX

Características

Aplicación	Measurement of vacuum values close to the suction pad Remote evaluation of the signals Processing the output signals, for example, by PLC
Medios	dry, oil-free air and non-aggressive gases
Rango de temperatura	0 - 50 °C
Señal de salida	1 to 5 analogous to V
Histéresis	Fixed: 20 mbar (model with digital sensor)
Long. cable	3 m
Tipo de protecc.	IP 40



Nota

Otras especificaciones a petición.

Descripción

Mini-sensor with housing and connection cable, analogue or digital output signal. Minimum size and low weight combined with high measuring accuracy.

Artículo

Denominación	Conexión	H (mm)	L (mm)	Rango de medición	Tensión
K- 07 45 01 56	M 5 male	16,9	21,0	-1 bis 0 bar	10 - 24 V DC