

K-VAKUUMSENSOR ANALOG

Vacuum sensor, analogue

HANSA FLEX

Caractéristiques

| | |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|
| Application | Measurement of vacuum values close to the suction pad Remote evaluation of the signals Processing the output signals, for example, by PLC |
| Médiums | dry, oil-free air and non-aggressive gases |
| Plage de température | 0 - 50 °C |
| Signal de sortie | 1 to 5 analogous to V |
| Hystérésis | Fixed: 20 mbar (model with digital sensor) |
| Longueur de câble | 3 m |
| Indice de protection | IP 40 |



Remarque

Autres informations sur demande.

Description

Mini-sensor with housing and connection cable, analogue or digital output signal. Minimum size and low weight combined with high measuring accuracy.

Article

| Désignation | Raccord | H (mm) | L (mm) | Plage de mesure | Tension |
|----------------|----------|-----------|-----------|-----------------|--------------|
| K- 07 45 01 56 | M 5 male | 16,9 | 21,0 | -1 bis 0 bar | 10 - 24 V DC |