


# SCHRAUBE M VZ

Vidinis šešiakampis varžtas

**HANSA FLEX**

## Savybės

|                    |                                |
|--------------------|--------------------------------|
| Konstrukcija       | Varžtas su vidiniu šešiakampiu |
| Norma              | DIN 912 (ISO 4762)             |
| Medžiaga           | Plienas 10.9                   |
| Paviršiaus apsauga | galvanised (tempered)          |



## Prekė

| Pavadinimas          | G    | L1<br>(mm) | SW<br>(mm) |
|----------------------|------|------------|------------|
| SCHRAUBE M 08-25 VZ  | M 8  | 25         | 6          |
| SCHRAUBE M 08-30 VZ  | M 8  | 30         | 6          |
| SCHRAUBE M 08-35 VZ  | M 8  | 35         | 6          |
| SCHRAUBE M 08-40 VZ  | M 8  | 40         | 6          |
| SCHRAUBE M 10-30 VZ  | M 10 | 30         | 8          |
| SCHRAUBE M 10-35 VZ  | M 10 | 35         | 8          |
| SCHRAUBE M 10-40 VZ  | M 10 | 40         | 8          |
| SCHRAUBE M 10-45 VZ  | M 10 | 45         | 8          |
| SCHRAUBE M 10-50 VZ  | M 10 | 50         | 8          |
| SCHRAUBE M 12-35 VZ  | M 12 | 35         | 10         |
| SCHRAUBE M 12-40 VZ  | M 12 | 40         | 10         |
| SCHRAUBE M 12-45 VZ  | M 12 | 45         | 10         |
| SCHRAUBE M 12-50 VZ  | M 12 | 50         | 10         |
| SCHRAUBE M 12-55 VZ  | M 12 | 55         | 10         |
| SCHRAUBE M 12-60 VZ  | M 12 | 60         | 10         |
| SCHRAUBE M 14-45 VZ  |      | 45         | 12         |
| SCHRAUBE M 14-50 VZ  |      | 50         | 12         |
| SCHRAUBE M 14-55 VZ  |      | 55         | 12         |
| SCHRAUBE M 14-60 VZ  |      | 60         | 12         |
| SCHRAUBE M 14-65 VZ  |      | 65         | 12         |
| SCHRAUBE M 14-70 VZ  |      | 70         | 12         |
| SCHRAUBE M 14-75 VZ  |      | 75         | 12         |
| SCHRAUBE M 14-80 VZ  |      | 80         | 12         |
| SCHRAUBE M 16-50 VZ  | M 16 | 50         | 14         |
| SCHRAUBE M 16-55 VZ  | M 16 | 55         | 14         |
| SCHRAUBE M 16-60 VZ  | M 16 | 60         | 14         |
| SCHRAUBE M 16-70 VZ  | M 16 | 70         | 14         |
| SCHRAUBE M 16-80 VZ  | M 16 | 80         | 14         |
| SCHRAUBE M 16-90 VZ  | M 16 | 90         | 14         |
| SCHRAUBE M 16-100 VZ | M 16 | 100        | 14         |
| SCHRAUBE M 20-60 VZ  | M 20 | 60         | 17         |
| SCHRAUBE M 20-65 VZ  | M 20 | 65         | 17         |
| SCHRAUBE M 20-70 VZ  | M 20 | 70         | 17         |
| SCHRAUBE M 20-90 VZ  | M 20 | 90         | 17         |
| SCHRAUBE M 20-100 VZ | M 20 | 100        | 17         |
| SCHRAUBE M 20-110 VZ | M 20 | 110        | 17         |
| SCHRAUBE M 20-120 VZ | M 20 | 120        | 17         |

SW = rakto dydis

## Gaminių variantai

SCHRAUBE M

## priedai šiems gaminiams

|               |                     |
|---------------|---------------------|
| FH (3000 PSI) | SAE flanšo pusė     |
| FH (6000 PSI) | SAE flanšo pusė     |
| VF (3000 PSI) | SAE ištinis flanšas |
| VF (6000 PSI) | SAE ištinis flanšas |