

# K-VAKUUMSENSOR ANALOG

Vacuum sensor, analogue

**HANSA FLEX**

## Īpašības

<b>Izmantošana</b>	Measurement of vacuum values close to the suction pad Remote evaluation of the signals Processing the output signals, for example, by PLC
<b>Darba vides</b>	dry, oil-free air and non-aggressive gases
<b>Temperatūras diapazons</b>	0 - 50 °C
<b>Izejas signāls</b>	1 to 5 analogous to V
<b>Histerēze</b>	Fixed: 20 mbar (model with digital sensor)
<b>Kabeļa garums</b>	3 m
<b>Aizsardzības veids</b>	IP 40



## Norāde

Citi dati pieejami pēc pieprasījuma.

## Apraksts

Mini-sensor with housing and connection cable, analogue or digital output signal. Minimum size and low weight combined with high measuring accuracy.

## Izstrādājums

Apzīmējums	Savienojums	H (mm)	L (mm)	Mērīšanas diapazons	Spriegums
K- 07 45 01 56	M 5 male	16,9	21,0	-1 bis 0 bar	10 - 24 V DC