


K-XVM ZYL 1

Male connectors, parallel male thread

HANSA FLEX



Wskazówka

Dalsze informacje na zapytanie.

Artykuł

| Oznaczenie | Gwint | dla węża | L1 (mm) | RK |
|----------------|-------|--------------|------------|-------|
| K- 07 40 30 03 | M 5 | 5 mm / 3 mm | 20,0 | 8 mm |
| K- 07 40 30 04 | G 1/8 | 6 mm / 4 mm | 27,0 | 14 mm |
| K- 07 40 30 05 | G 1/8 | 8 mm / 6 mm | 29,0 | 14 mm |
| K- 07 40 30 06 | G 1/4 | 6 mm / 4 mm | 29,0 | 17 mm |
| K- 07 40 30 07 | G 1/4 | 8 mm / 6 mm | 31,0 | 17 mm |
| K- 07 40 30 08 | G 1/4 | 10 mm / 8 mm | 33,0 | 17 mm |
| K- 07 40 30 09 | G 3/8 | 8 mm / 6 mm | 33,0 | 19 mm |
| K- 07 40 30 10 | G 3/8 | 10 mm / 8 mm | 35,0 | 19 mm |
| K- 07 40 30 11 | G 3/8 | 12 mm / 9 mm | 35,0 | 19 mm |
| K- 07 40 30 12 | G 1/2 | 10 mm / 8 mm | 36,0 | 24 mm |
| K- 07 40 30 13 | G 1/2 | 12 mm / 9 mm | 36,0 | 24 mm |