


K-VAKUUMSENSOR ANALOG

Vacuum sensor, analogue

HANSA FLEX

Vlastnosti

| | |
|------------------------|---|
| Použitie | Measurement of vacuum values close to the suction pad Remote evaluation of the signals Processing the output signals, for example, by PLC |
| Médiá | dry, oil-free air and non-aggressive gases |
| Rozsah teplôt | 0 - 50 °C |
| Výstupný signál | 1 to 5 analogous to V |
| Hysterézia | Fixed: 20 mbar (model with digital sensor) |
| Dĺžka kábla | 3 m |
| Krytie | IP 40 |



Poznámka

Ďalšie údaje na vyžiadanie.

Popis

Mini-sensor with housing and connection cable, analogue or digital output signal. Minimum size and low weight combined with high measuring accuracy.

Výrobok

| Označenie | Prípojka | V (mm) | D (mm) | Rozsah merania | Napätie |
|----------------|----------|-----------|-----------|----------------|--------------|
| K- 07 45 01 56 | M 5 male | 16,9 | 21,0 | -1 bis 0 bar | 10 - 24 V DC |