

# K-BIMETALLTHERMOMETER 46

Bimetallic thermometers

**HANSA FLEX**

## Lastnosti

|                  |                                   |
|------------------|-----------------------------------|
| tip              | 46                                |
| popravek prikaza | On end of stem                    |
| Obratovalni tlak | Max. 6 bar (on thermowell)        |
| zaščitna cev     | Clamped (removable), copper alloy |
| ohišje           | Plastic                           |
| kontrolno okence | Plexiglass                        |



## Navodilo

Drugi podatki na zahtevo.

## Opis

Applications: Heating, plumbing, universal.

## Artikel

| Opis           | območja prikaza | Ø<br>(mm) | dolžina potopne ročice | Navoj |
|----------------|-----------------|-----------|------------------------|-------|
| K- 07 20 09 86 | 0 °C to +60 °C  | 63,0      | 40 mm                  | G 1/2 |
| K- 07 20 09 87 | 0 °C to +120 °C | 63,0      | 40 mm                  | G 1/2 |
| K- 07 20 09 88 | 0 °C to +60 °C  | 63,0      | 60 mm                  | G 1/2 |
| K- 07 20 09 89 | 0 °C to +120 °C | 63,0      | 60 mm                  | G 1/2 |
| K- 07 20 09 90 | 0 °C to +60 °C  | 63,0      | 100 mm                 | G 1/2 |
| K- 07 20 09 91 | 0 °C to +120 °C | 63,0      | 100 mm                 | G 1/2 |
| K- 07 20 10 19 | 0 °C to +60 °C  | 80,0      | 40 mm                  | G 1/2 |
| K- 07 20 10 20 | 0 °C to +120 °C | 80,0      | 40 mm                  | G 1/2 |
| K- 07 20 10 21 | 0 °C to +60 °C  | 80,0      | 60 mm                  | G 1/2 |
| K- 07 20 10 22 | 0 °C to +120 °C | 80,0      | 60 mm                  | G 1/2 |
| K- 07 20 10 23 | 0 °C to +60 °C  | 80,0      | 100 mm                 | G 1/2 |
| K- 07 20 10 24 | 0 °C to +120 °C | 80,0      | 100 mm                 | G 1/2 |