


K-VTST 3 AB MS

Distributor pieces, brass, with 3 outlets

HANSA FLEX

Lastnosti

Priključek	G 3/4 and G 1 incl. PTFE-sealing at outer thread, G 1 1/4 without sealing
Obratovalni tlak	maks. 10 bar



Navodilo

Drugi podatki na zahtevo.

Opis

For assembling compressed air taps. End fittings with 1 x male and 1 x female thread, outlets optionally with male or female thread.

Artikel

Opis	izhodni priključek	vhodni priključek	C (mm)	L (mm)
K- 07 40 40 55	3 x 1/2 male	2 x 3/4	50,0	160,0
K- 07 40 40 56	3 x 1/2 female	2 x 3/4	50,0	160,0
K- 07 40 40 57	3 x 1/2 male	2 x 1	50,0	163,0
K- 07 40 40 58	3 x 1/2 female	2 x 1	50,0	163,0
K- 07 40 40 59	3 x 1/2 male	2 x 1 1/4	60,0	197,0
K- 07 40 40 60	3 x 1/2 female	2 x 1 1/4	60,0	197,0