

GMM 100 HKR

注有甘油的压力表

HANSA FLEX

属性

| | |
|--------|---|
| 结构类型 | Pipe spring pressure gauge with glycerine filling |
| 固定 | 夹紧环 |
| 接口 1 | BSP外螺纹,圆柱形 |
| 密封形式 1 | 带塞扁平密封 |
| 接口 | 后,偏心 |
| 标准 | EN 837-1 |
| 缓冲 | 通过甘油注入 |
| 温度范围 | medium max. +60 °C Ambient -20 °C to +60 °C |



提示

静止负荷时的应用范围: 至刻度盘终端读数。

交变负荷时应用范围: 至0.9倍的刻度盘终端读数。

货品

| 名称 | 额定大小 Ø | 刻度范围 | 质量等级 | 接口 |
|------------------|--------|----------|------|------------|
| GMM 100-0.6 HKR | 100 | 0...0,6 | 1,0 | G 1/2" -14 |
| GMM 100-1 HKR | 100 | 0...1 | 1,0 | G 1/2" -14 |
| GMM 100-1.6 HKR | 100 | 0...1,6 | 1,0 | G 1/2" -14 |
| GMM 100-2.5 HKR | 100 | 0...2,5 | 1,0 | G 1/2" -14 |
| GMM 100-4 HKR | 100 | 0...4 | 1,0 | G 1/2" -14 |
| GMM 100-6 HKR | 100 | 0...6 | 1,0 | G 1/2" -14 |
| GMM 100-10 HKR | 100 | 0...10 | 1,0 | G 1/2" -14 |
| GMM 100-16 HKR | 100 | 0...16 | 1,0 | G 1/2" -14 |
| GMM 100-25 HKR | 100 | 0...25 | 1,0 | G 1/2" -14 |
| GMM 100-40 HKR | 100 | 0...40 | 1,0 | G 1/2" -14 |
| GMM 100-60 HKR | 100 | 0...60 | 1,0 | G 1/2" -14 |
| GMM 100-100 HKR | 100 | 0...100 | 1,0 | G 1/2" -14 |
| GMM 100-160 HKR | 100 | 0...160 | 1,0 | G 1/2" -14 |
| GMM 100-250 HKR | 100 | 0...250 | 1,0 | G 1/2" -14 |
| GMM 100-400 HKR | 100 | 0...400 | 1,0 | G 1/2" -14 |
| GMM 100-600 HKR | 100 | 0...600 | 1,0 | G 1/2" -14 |
| GMM 100-1000 HKR | 100 | 0...1000 | 1,0 | G 1/2" -14 |