


属性

工作压力	最大12巴
工作温度	-20 °C to +70 °C



提示

其它数据应客户要求提供。

描述

With granular filling, self-cleaning. The spherical shape of the granules allows very fine dust to escape in addition to air. Higher blow-off rate.

货品

名称	螺纹	A (mm)	B (mm)	C (mm)
K-07 40 14 51	G 1/8	6,0	33,0	15,0
K-07 40 14 52	G 1/4	8,0	43,0	19,0
K-07 40 14 53	G 3/8	11,0	57,0	24,5
K-07 40 14 54	G 1/2	11,0	57,0	24,5
K-07 40 14 55	G 3/4	17,5	112,0	48,0
K-07 40 14 56	G 1	16,0	110,5	48,0